

## **Universal Control 2.5.1 Milestone Release Notes**

12/18/17

### **Version Information:**

- Universal Control (Mac/PC) - 2.5.1.45526
- UC Surface (iOS/Android) - 2.5.0.45267
- QMix-UC (iOS/Android) - 2.4.0.25212
- Capture (Mac/PC) - 2.3.6.45267

### **New In This Release:**

- Mac/PC update only (no update for iOS/Android or Capture)
- Includes firmware update for Quantum to fix headphone routing issue with ADAT streams
- Includes firmware update for Studio 192 that fixes potential audio artifact issues

### **The Follow Android devices should be Compatible with UC Surface:**

- Any device running Android 5.0 or later with a minimum screen resolution of 1024x768

### **The Follow Android devices should be Compatible with Qmix-UC:**

- Any device running Android 5.0 or later

*NOTE: It is not possible to qualify all devices that support Android 5.0 or later. Any device running Android 5.0+ should work, but support and functionality may vary. 1024x768 resolution required for UC Surface.*

### **The Following iOS devices are Compatible with UC Surface (running iOS 9.3 or later):**

- iPad (2nd generation)
- iPad (3rd generation)
- iPad (4th generation)
- iPad Mini
- iPad Mini 2
- iPad Mini 3
- iPad Mini 4
- iPad Air
- iPad Air 2
- iPad Pro

### **The Following iOS devices are Compatible with QMix-UC (running iOS 9.3 or later):**

- iPhone 4S
- iPhone 5
- iPhone 5C
- iPhone 5S
- iPhone 6
- iPhone 6 Plus
- iPhone 6S
- iPhone 6S Plus
- iPhone SE
- iPhone 7
- iPhone 7 Plus

- iPhone 8
- iPhone 8 Plus
- iPhone X (not yet tested, but assumed to be compatible)
- iPod touch (5th Generation)
- iPod touch (6th Generation)

**UC 2.5 Supports the following Operating Systems:**

- Windows 7 Service Pack 1 + Platform Update (32 bit & 64 bit)
- Windows 8.1 (32 bit & 64 bit)
- Windows 10 (32 bit & 64 bit)
- OS X 10.8.5 (Mountain Lion)
- OS X 10.9 (Mavericks)
- OS X 10.10 (Yosemite)
- OS X 10.11 (El Capitan)
- OS X 10.12 (Sierra)
- OS X 10.13 (High Sierra)

**Capture 2.3 is compatible with the following PreSonus Hardware and Software:**

- StudioLive 16.4.2 classic
- StudioLive 24.4.2 classic
- StudioLive 16.0.2 classic
- StudioLive 16.0.2 USB
- StudioLive 16.4.2AI
- StudioLive 24.4.2AI
- StudioLive 32.4.2AI
- StudioLive RM32AI
- StudioLive RM16AI
- StudioLive RML32AI
- StudioLive RML16AI
- StudioLive AR8
- StudioLive AR12
- StudioLive AR16
- StudioLive AR22
- StudioLive 32 Series III Console Mixer
- StudioLive 24 Series III Console Mixer
- StudioLive 16 Series III Console Mixer
- StudioLive 32R Series III Rack Mixer
- StudioLive 24R Series III Rack Mixer
- StudioLive 16R Series III Rack Mixer
- UC Surface 2.5.1

**UC 2.5.1 Does Not Support the Following Legacy Operating Systems:**

- Versions of Windows 7 earlier than Service Pack 1 + Platform Update
- Windows 8 (users should update to Windows 8.1)

## **Fixed In This Release:**

### **Quantum:**

- Quantum headphones now reference ADAT output streams as expected

### **Studio 192:**

- Potential audio artifacts during recording/playback now fixed

## **Known Issues:**

### **UC Surface**

- Control and metering on UC Surface instance connected via Firewire may exhibit lag on some systems
- Copy, Delete, & Rename Local Scenes for Cascaded mixers not functioning as expected
- RM/RML: Fat Channel Reset Button Does Not Reset the HPF (or LPF)
- RM/RML: FX issues with Cascaded RM/RML mixers
  - UC Surface and CS18 not controlling some of Slave mixer's FX Bus settings (volume, mute, Pre/Post)
- AI/RM/Studio Interfaces: FX Preset list does not update automatically when selecting FX Busses (must exit FX and return to update preset list)
- AI/RM Mixers: FX Bus Master is missing HPF control
- AI/RM Mixers: Restoring a Mixer Backup over Firewire is not possible.
  - Must be done over Network connection
- AI/RM Mixers: Auxiliary Firewire Input 52 driver label is incorrect
- AI/RM Mixers: Users on OS X 10.8.5 may experience a firewire driver installation issue (to be fixed in UC 2.5)
- AI Consoles: Solo level missing from Settings page
- AI Consoles: Channel Type and Channel Color not persistent or shared across clients
  - Not implemented in firmware yet

### **Capture**

- Playback routing incorrect with cascaded classic StudioLive 16.4.2 consoles

Join our community of PreSonus users on the [PreSonus Answers](#) site for information and product support. While you're there, don't forget to vote for your favorite feature requests.

Alternatively, you can visit our [Knowledge Base](#) for more informative articles authored by the support staff. To log a support ticket or contact technical support, please visit [MyPreSonus](#).