

## **Version Information:**

- Universal Control (Mac/PC) - v3.4.1.63149
- UC Surface (iOS/Android) - v3.4.1.63149
- QMix-UC (iOS/Android) - v3.1.0.54974 (*Adds support for SL16.0.2 Firewire and Quantum 2626*)
- Capture (Mac/PC) - v3.0.4.63149

## **Supported OS Versions:**

- OS X 10.13.6 (High Sierra) or later
- Windows 10 (x64) v1709 or later
- Android 6.0 Marshmallow or later
- iOS 10 or later

## **New In This Release:**

- Reveletor firmware and UI updates
- Quantum family firmware update
- Silent install now supported for the AudioBox family driver

## **Fixed In This Release:**

- External Clock Source now retained on reboot\*\*
- ADAT noise issue resolved for Quantum 26x32

## **Known Issues:**

### **UC Surface**

- Copy, Delete, & Rename Local Scenes for Cascaded AI mixers not functioning as expected

### **Quantum Interface Family**

- \*\*Clocking improvements still ongoing for Quantum 4848

### **AI/RM Mixers**

- Fat Channel Reset Button Does Not Reset the HPF (or LPF)
- FX issues with Cascaded RM/RML mixers
  - UC Surface and CS18 not controlling some of Slave mixer's FX Bus settings (volume, mute, Pre/Post)
- FX Preset list does not update automatically when selecting FX Busses (must exit FX and return to update preset list)
- FX Bus Master is missing HPF control
- Auxiliary Firewire Input 52 driver label is incorrect
- Users on OS X 10.8.5 may experience a firewire driver installation issue (to be fixed in UC 2.5)
- Solo level missing from Settings page
- Channel Type and Channel Color not persistent or shared across clients
  - Not implemented in firmware yet

### **Series III DAW Mode**

- When viewing a send or cue mix, send labels should be placed in the scribble strips
- Incorrect preamp gain range on mixer display when using TRS inputs
- Meters don't match between DAW mode and Mixer mode
- Channel parameters may not populate in Fat Channel after opening song
- Series III Automation Control: Bypass Button Not Present

- Newly added Plugin not automatically selected and controls not on FatCh Encoder section if another Plugin wasn't already selected when adding the new Plugin
- Talkback Button Does Not Light Up In UCS When Engaged From S1
- Channel Input Does Not Have Selection For "None"
- Unity Fader Value Is Not Accurate
- There Is No Way To Remove A Channel Insert
- Write Select Channel Should Turn Red Like FaderPort 8 & 16
- Pressing Inputs layer button should open Inputs section in S1 Console
- Adding Send while viewing Sends view doesn't update fader level
- Select Buttons For Multi-Channel Instrument Outputs Do Not Light Up
- On Big Sur 11.2, control of Logic or other DAWs via MIDI
- On Big Sur 11.2 scribble strip displays render incorrectly

#### **FaderPort 8 and 16**

- A restart of Pro Tools and FaderPort may be required if the FaderPort loses power when using Pro Tools

#### **ATOM SQ**

- Occasionally ATOM SQ's pad LEDs do not light up correctly while using Studio One 5. [More info can be found here.](#)
- On Big Sur 11.2, ATOM SQ does not display in Universal Control or Audio MIDI Setup on Intel-based Macs
- On Big Sur 11.2, ATOM SQ does not establishing Native Mode connectivity with Studio One 5 on Arm-Based Macs

Join our forum community of PreSonus users on the [PreSonus Forum](#). Submit and vote for feature requests on the [PreSonus Answers](#) site. Visit our [Knowledge Base](#) for more informative articles authored by the support staff. To log a support ticket or contact technical support, please visit [MyPreSonus](#).