

Version Information:

- Universal Control (Mac/PC) - v3.2.0.56558
- UC Surface (iOS/Android) - v3.2.0.56558
- QMix-UC (iOS/Android) - v3.1.0.54974 (*Adds support for SL16.0.2 Firewire and Quantum 2626*)
- Capture (Mac/PC) - v3.0.3.56558
- FaderPort (2018) / FaderPort 8 / FaderPort 16 - v3.42

NOTE: If updating from FaderPort 16 firmware earlier than v3.32, Universal Control will prompt for a manual reboot in order to complete the update process

- Quantum Series - Driver 1.28
- StudioLive 1602 USB - XMOS v 0.05

Supported OS Versions:

- OS X 10.11.6 (El Capitan) or later
- Windows 7 (x64) Service Pack 1 + Platform Update, Windows 8.1 (x64), Windows 10 (x64) Version 1809 or later
- Android 5.1.1 Lollipop or later
- iOS 10 or later

New In This Release:

- Updated Windows USB Audio Device Driver
- Support for StudioLive 16.0.2 Firewire
- Separate firewire driver installer included in UC download to accommodate OS X Catalina
- Firmware version/update improvements for EarMix, NSB 8.8, & NSB 16.8
- FaderPort 8/16 - on-the-fly MIDI Operation mode switching
- FaderPort 16 - HUI automation modes now works properly channels 9-16
- Adds support for ioStation 24c
- Meter Decay speed selections added for Series III and AI Mixers

Fixed In This Release:

- Series III mixers - Digital Patching no longer available in UC with non-admin User Profile
- AI Mixers - Universal Control now requests microphone access on OS X Mojave and Catalina for SMAART support
- Network MIDI now connects properly when mixer also has USB connected

Known Issues:

UC Surface

- Copy, Delete, & Rename Local Scenes for Cascaded AI mixers not functioning as expected

AI/RM Mixers

- Fat Channel Reset Button Does Not Reset the HPF (or LPF)
- FX issues with Cascaded RM/RML mixers
 - UC Surface and CS18 not controlling some of Slave mixer's FX Bus settings (volume, mute, Pre/Post)
- FX Preset list does not update automatically when selecting FX Busses (must exit FX and return to update preset list)
- FX Bus Master is missing HPF control
- Restoring a Mixer Backup over Firewire is not possible.
 - Must be done over Network connection
- Auxiliary Firewire Input 52 driver label is incorrect

- Users on OS X 10.8.5 may experience a firewire driver installation issue (to be fixed in UC 2.5)
- Solo level missing from Settings page
- Channel Type and Channel Color not persistent or shared across clients
 - Not implemented in firmware yet

DAW Mode

- When viewing a send or cue mix, send labels should be placed in the scribble strips
- Incorrect preamp gain range on mixer display when using TRS inputs
- Meters don't match between DAW mode and Mixer mode
- Channel parameters may not populate in Fat Channel after opening song
- Series III Automation Control: Bypass Button Not Present
- Newly added Plugin not automatically selected and controls not on FatCh Encoder section if another Plugin wasn't already selected when adding the new Plugin
- Talkback Button Does Not Light Up In UCS When Engaged From S1
- Channel Input Does Not Have Selection For "None"
- Unity Fader Value Is Not Accurate
- There Is No Way To Remove A Channel Insert
- Write Select Channel Should Turn Red Like FaderPort 8 & 16
- Pressing Inputs layer button should open Inputs section in S1 Console
- Adding Send while viewing Sends view doesn't update fader level
- Select Buttons For Multi-Channel Instrument Outputs Do Not Light Up

FaderPort 8 and 16

- A restart of Pro Tools and FaderPort may be required if the FaderPort loses power when using Pro Tools

ATOM

- MIDI event velocities cannot be adjusted by ATOM with some Studio One settings setups

Join our forum community of PreSonus users on the [PreSonus Forum](#). Submit and vote for feature requests on the [PreSonus Answers](#) site. Visit our [Knowledge Base](#) for more informative articles authored by the support staff. To log a support ticket or contact technical support, please visit [MyPreSonus](#).