

## **Version Information:**

- Universal Control (Mac/PC) - v3.3.0.59348
- UC Surface (iOS/Android) - v3.2.1.57677
- QMix-UC (iOS/Android) - v3.1.0.54974 (*Adds support for SL16.0.2 Firewire and Quantum 2626*)
- Capture (Mac/PC) - v3.0.3.57677
- FaderPort (2018) / FaderPort 8 / FaderPort 16 - v3.42

**NOTE: If updating from FaderPort 16 firmware earlier than v3.32, Universal Control will prompt for a manual reboot in order to complete the update process**

- The original FaderPort will no longer be supported in Universal Control from this version forward
- Quantum Series - Driver 1.28
- StudioLive 1602 USB - XMOS v 0.05

## **Supported OS Versions:**

- OS X 10.13.6 (High Sierra) or later
- Windows 10 (x64) v1709 or later
- Android 6.0 Marshmallow or later
- iOS 10 or later

## **New In This Release:**

- Adds support for ATOM SQ

## **Known Issues:**

### **UC Surface**

- Copy, Delete, & Rename Local Scenes for Cascaded AI mixers not functioning as expected

### **AI/RM Mixers**

- Fat Channel Reset Button Does Not Reset the HPF (or LPF)
- FX issues with Cascaded RM/RML mixers
  - UC Surface and CS18 not controlling some of Slave mixer's FX Bus settings (volume, mute, Pre/Post)
- FX Preset list does not update automatically when selecting FX Busses (must exit FX and return to update preset list)
- FX Bus Master is missing HPF control
- Restoring a Mixer Backup over Firewire is not possible.
  - Must be done over Network connection
- Auxiliary Firewire Input 52 driver label is incorrect
- Users on OS X 10.8.5 may experience a firewire driver installation issue (to be fixed in UC 2.5)
- Solo level missing from Settings page
- Channel Type and Channel Color not persistent or shared across clients
  - Not implemented in firmware yet

### **Series III DAW Mode**

- When viewing a send or cue mix, send labels should be placed in the scribble strips
- Incorrect preamp gain range on mixer display when using TRS inputs
- Meters don't match between DAW mode and Mixer mode
- Channel parameters may not populate in Fat Channel after opening song
- Series III Automation Control: Bypass Button Not Present
- Newly added Plugin not automatically selected and controls not on FatCh Encoder section if another Plugin wasn't already selected when adding the new Plugin

- Talkback Button Does Not Light Up In UCS When Engaged From S1
- Channel Input Does Not Have Selection For "None"
- Unity Fader Value Is Not Accurate
- There Is No Way To Remove A Channel Insert
- Write Select Channel Should Turn Red Like FaderPort 8 & 16
- Pressing Inputs layer button should open Inputs section in S1 Console
- Adding Send while viewing Sends view doesn't update fader level
- Select Buttons For Multi-Channel Instrument Outputs Do Not Light Up

#### **FaderPort 8 and 16**

- A restart of Pro Tools and FaderPort may be required if the FaderPort loses power when using Pro Tools

#### **ATOM**

- MIDI event velocities cannot be adjusted by ATOM with some Studio One settings setups

Join our forum community of PreSonus users on the [PreSonus Forum](#). Submit and vote for feature requests on the [PreSonus Answers](#) site. Visit our [Knowledge Base](#) for more informative articles authored by the support staff. To log a support ticket or contact technical support, please visit [MyPreSonus](#).