

Universal Control 1.8.3 Release Notes

Version Information:

UC 1.8 (Mac/PC) v1.8.3.40882

FaderPort firmware v1.01

NEW in UC 1.8.3

- Updated driver certificates for Windows 10 support
- FaderPort 8 support

NOTES:

- AudioBox interface support (driver and control panel only, no VSL software)
- The "AB1818VSL" remote App is NOT compatible with UC 1.8 and later

UC 1.8.3 Supports the following Operating Systems:

- Windows 7 Service Pack 1 + Platform Update (32 bit & 64 bit)
- Windows 8.1 (32 bit & 64 bit)
- Windows 10 (32 bit & 64 bit)
- OS X 10.9 (Mavericks)
- OS X 10.10 (Yosemite)
- OS X 10.11 (El Capitan)
- OS X 10.12 (Sierra)

Current iOS App versions Compatible with the StudioLive AI family mixers (available on the iTunes App Store):

- UC Surface version 1.8.1.39355
- QMix-AI version 1.3.39307

The Following iOS devices are Compatible with UC Surface (running iOS 8 or later):

- iPad (2nd generation)
- iPad (3rd generation)
- iPad (4th generation)
- iPad Mini
- iPad Mini 2
- iPad Mini 3
- iPad Mini 4
- iPad Air
- iPad Air 2
- iPad Pro

The Following iOS devices are Compatible with QMix AI (running iOS 8 or later):

- iPhone 4S
- iPhone 5
- iPhone 5C
- iPhone 5S
- iPhone 6

- iPhone 6 Plus
- iPhone 6S
- iPhone 6S Plus
- iPhone SE
- iPhone 7
- iPhone 7 Plus
- iPod touch (5th Generation)
- iPod touch (6th Generation)

UC 1.8.1 Does Not Support the Following Legacy Operating Systems:

- Versions of Windows 7 earlier than Service Pack 1 + Platform Update
- Windows 8 (users should update to Windows 8.1)

Known Issues:

CS18:

- Monitor bus Cue Edit screen doesn't reflect linked mixes
- CS18 Custom Talkback assigns not synced with UC Surface Talkback assigns
- CS18 exits FX Screen when switching channels
- Fat Channel Equalizer Q Decimal Places Are Cut Off
- Subgroup Edit Screen Missing TB, Tape In, & Dig Ret
- Tap Assign not retained with scenes or power cycle of CS18

UC Surface:

- RM Mixers Fat Channel Reset Button Does Not Reset the HPF (or LPF)
- Auxiliary Firewire Input 52 driver label is incorrect
- Restoring a Mixer Backup over Firewire is not possible. Must be done over Network connection
- Name changes sometimes do not update on iOS
- iOS Demo Mode not working

AI Consoles:

- Some knobs control Universal Control channel ghost faders in Locate Mode
- Lockout Mode does not disable Mutes or Fat Channel controls
- Smart features not working/supported for Cascaded AI Consoles
- Mixer backup files will not restore over firewire (must use network connection with UC Surface to restore backup files)

RM Mixers:

- Cascaded RM Mixers Tape In on Slave mixer not controlled from Master

Capture 2:

- Playback routing incorrect with cascaded classic StudioLive 16.4.2 consoles

FaderPort 8:

- Panning graphic shows as off center when it is centered in the DAW
- Turning Pan knob too fast creates sporadic behavior
- Pan graphic appears when DAW is closed or session is closed

- ProTools (HUI) - Redo button does an Undo command
- ProTools (HUI) - "Mins:Secs" and "Samples" timecode formats not supported
- Logic (MCU) - only "Hours:Mins:seconds"ms" timecode format supported
- Logic (MCU) - timecode shifted outside proper labels
- Sonar - cannot switch between fader focused modes, i.e. Track, Aux, or Main focus.

Join our community of PreSonus users on the [PreSonus Forum](#) for information, user-based support, tips and tricks, and more.

Alternatively, you can visit our [Knowledge Base](#) for more informative articles authored by the support staff.

To log a support ticket or contact technical support, please visit [My.PreSonus](#)