

Worx Control 1.4

Release Notes Date: 10-28-2019

OS Support:

- Windows 10 x64 (build 1703) minimum
- macOS 10.12 (Sierra), macOS 10.13 (High Sierra), macOS 10.14 Mojave, macOS 10.15 (Catalina)

Version Information:

- Worx Control 1.4.54335

Firmware compatible with this version:

- v1.3.16302 (PDA1000 & PDA2000 amp models)

Fixed or added in this release:

- Added support for OS X 10.15 Catalina
-

Worx Control 1.3

Release Notes Date: 8-14-2019

OS Support:

- Windows 7 SP1 + Platform Update 64-Bit, Windows 8.1 64-Bit, and Windows 10 x64 (build 1703) minimum.
- Mac OSX 10.11 (El Capitan) macOS 10.12 (Sierra), macOS 10.13 (High Sierra), macOS 10.14 Mojave

Version Information:

- Worx Control 1.3.53382

Firmware released with this version:

- v1.3.16302 (PDA1000 & PDA2000 amp models)

Fixed or added in this release:

- Added support for new Worx model S-UM1.5 (PDA1000 amp)
 - Improved Input Meter display graphic
 - Improved Input metering (Post-ADC)
 - Resolved an issue with incorrect input clip detection
 - Speaker Name in the main control page will turn red when output limiter is engaged
-

Worx Control 1.2

Release Notes Date: 12-21-18

OS Support:

- Windows 7 SP1 + Platform Update 64-Bit, Windows 8.1 64-Bit, and Windows 10 x64 (build 1703) minimum.
- Mac OSX 10.11 (El Capitan) macOS 10.12 (Sierra), macOS 10.13 (High Sierra), macOS 10.14 Mojave

Version Information:

- Worx Control 1.2.49773

Firmware released with this version:

- PDA 1000 Series Amplifiers with CDL 12 / CDL 18 - Firmware v15198

Fixed or added in this release:

- Firmware update for Worx Series Loudspeakers
- Added CDL-Series
- Firmware 15198 with CDL - Clip light comes on too early
- Worx Control 1.2.49773 - Dragging a muted speaker in Worx Control would unmute it.