Universal Control 3.6.4 Milestone Release Notes   5/10/2022

Version Information:
- Universal Control (Mac/PC) - v3.6.4.87069
- UC Surface (iOS/Android) - v3.6.4.87069
- QMix-UC (iOS/Android) - v3.1.0.54974
- Capture (Mac/PC) - v3.1.0.66460
- Studio Series (1824c) firmware - v3.11
- Studio 192 / Studio 192 Mobile firmware - v1.8-44 / 1.29
- Revelator Firmware v1.51
- Revelator Dynamic Firmware v1.14

Supported OS Versions:
- OS X 10.13.6 (High Sierra) or later
- Windows 10 (x64) v1709 or later **(Windows 11 supported in this release)**
- Android 6.0 Marshmallow or later
- iOS 10 or later

Fixed In This Release:

- Firmware update to prevent preamp noise in Studio 1824c under certain bootup conditions
- Studio 192 control panel in Universal Control no longer crashes when muting all channels of mixes
- Studio 192 added an error message to MacOS about invalid clock source (macOS 12.3 or higher)
- Revelator Dynamic - minor bug fixes and improvements
- Revelator - fixes an issue where firmware update 1.50 in UC 3.6.3 causes Revelator to no longer be seen by Universal Control 3.6.3.

Known Issues:

Series III DAW Mode
- When viewing a send or cue mix, send labels should be placed in the scribble strips
- Incorrect preamp gain range on mixer display when using TRS inputs
- Meters don't match between DAW mode and Mixer mode
- Channel parameters may not populate in Fat Channel after opening song
- Series III Automation Control: Bypass Button Not Present
- Newly added Plugin not automatically selected and controls not on FatCh Encoder section if another Plugin wasn't already selected when adding the new Plugin
- Talkback Button Does Not Light Up In UCS When Engaged From S1
- Channel Input Does Not Have Selection For "None"
- Unity Fader Value Is Not Accurate
- There Is No Way To Remove A Channel Insert
- Write Select Channel Should Turn Red Like FaderPort 8 & 16
- Pressing the Inputs layer button should open the Inputs section in S1 Console
- Adding Send while viewing Sends view doesn't update fader level
- Select Buttons For Multi-Channel Instrument Outputs Do Not Light Up
- On Big Sur 11.2, control of Logic or other DAWs via MIDI
- On Big Sur 11.2 scribble strip displays render incorrectly

Join our forum community of PreSonus users on the PreSonus Forum. Submit and vote for feature requests on the PreSonus Answers site. Visit our Knowledge Base for more informative articles authored by the support staff. To log a support ticket or contact technical support, please visit MyPreSonus.