

Version Information:

- Universal Control (Mac/PC) - v4.1.0.93124
- UC Surface (iOS/Android) - v4.1.0.93124
- QMix-UC (iOS/Android) - v3.2.2.92582
- Capture (Mac/PC) - v3.1.0.66460
- FaderPort 2018,8,16 Firmware - v3.74
- Revelator io44 Firmware - v1.22
- StudioLive Series III Exosystem -
 - Series III Firmware - v2.7.0.92826
 - NSB Firmware - v1.4.0.87732
 - EarMix Firmware - v1.4.0.88061
 - SW5E Firmware - v1.5.0.93282
 - AVB-D16 Firmware – v1.0.0.17358

Supported OS Versions:

- macOS 10.14.6 (Mojave) or later
- Windows 10 (x64) 20H1 or later
- Windows 11
- Android 6.0 (Marshmallow) or later
- iOS 11.4 or later

NOTE: There is an update to the UC Metro Public Beta release in this official version of Universal Control that requires both host and client to be on UC 4.1 as well as Series III firmware 2.7 in order for Metro connection to work as expected.

New In This Release:

Universal Control

- Notification of incompatible AVB Streams with Series III devices

Series III

- Notification of incompatible AVB Streams with Series III devices

Fixed In This Release:

Universal Control

- SW5E controls now present and working in UC

QMix-UC

- Wheel of Me control no longer lost after device sleep
- Screen rotation from vertical to landscape no longer hides Sub Mixes in Edit View

Series III

- Plugin Add-ons now retained once installed on mixer
- Pro Tools DAW Mode fix
- GEQ - Mini view EQ curve bars now drawn incorrectly
- Mixes now retain last channel selected when switching back to Mix

Quantum Family

- Quantum 2626 BSOD on DFU in Windows 10/11 with Titan Ridge

Revelator Family

- IO24 now retains 48V after power-cycle
- Fat Channel on USB Streams Feature won't toggle

Known Issues:

Series III DAW Mode

- When viewing a send or cue mix, send labels should be placed in the scribble strips
- Incorrect preamp gain range on mixer display when using TRS inputs
- Meters don't match between DAW mode and Mixer mode
- Channel parameters may not populate in Fat Channel after opening song
- Series III Automation Control: Bypass Button Not Present
- Newly added Plugin not automatically selected and controls not on FatCh Encoder section if another Plugin wasn't already selected when adding the new Plugin
- Talkback Button Does Not Light Up In UCS When Engaged From S1
- Channel Input Does Not Have Selection For "None"
- Unity Fader Value Is Not Accurate
- There Is No Way To Remove A Channel Insert
- Write Select Channel Should Turn Red Like FaderPort 8 & 16
- Pressing the Inputs layer button should open the Inputs section in S1 Console
- Adding Send while viewing Sends view doesn't update fader level
- Select Buttons For Multi-Channel Instrument Outputs Do Not Light Up
- On Big Sur 11.2, control of Logic or other DAWs via MIDI
- On Big Sur 11.2 scribble strip displays render incorrectly

Join our forum community of PreSonus users on the [PreSonus Forum](#). Submit and vote for feature requests on the [PreSonus Answers](#) site. Visit our [Knowledge Base](#) for more informative articles authored by the support staff. To log a support ticket or contact technical support, please visit [MyPreSonus](#).