

Version Information:

- StudioLive Series III (all models) - v2.2.16741
- NSB 16.8 - v1.2.16705
- NSB 8.8 - v1.2.16705
- EarMix - v1.2.16705
- SW5E - v1.2.16705

Supporting Software:

- Universal Control (Mac/PC) - v3.2.0.56558
- UC Surface (iOS/Android) - v3.2.0.56558
- QMix-UC (iOS/Android) - v3.1.0.54974
- Capture (Mac/PC) - v3.0.3.56558

Capture 3.0 is compatible with the following PreSonus Hardware and Software:

- StudioLive 16.4.2 classic
- StudioLive 24.4.2 classic
- StudioLive 16.0.2 classic
- StudioLive 16.0.2 USB
- StudioLive 16.4.2AI
- StudioLive 24.4.2AI
- StudioLive 32.4.2AI
- StudioLive RM32AI
- StudioLive RM16AI
- StudioLive RML32AI
- StudioLive RML16AI
- StudioLive AR8
- StudioLive AR12
- StudioLive AR16
- StudioLive AR22
- StudioLive AR8c
- StudioLive AR12c
- StudioLive AR16c
- StudioLive 32 Series III Console Mixer
- StudioLive 24 Series III Console Mixer
- StudioLive 16 Series III Console Mixer
- StudioLive 64S Series III Console Mixer
- StudioLive 32S Series III Console Mixer
- StudioLive 32SX Series III Console Mixer
- StudioLive 32SC Series III Console Mixer
- StudioLive 32R Series III Rack Mixer
- StudioLive 24R Series III Rack Mixer
- StudioLive 16R Series III Rack Mixer
- UC Surface 3.2

New In This Release:

- Firmware update with AVB network stability improvements for Series III, NSB 8/16, & EarMix
- Acceleration added to Series III Console screen scrolling for smoother navigation experience

Fixed In This Release:

StudioLive Series III Firmware

- Toggling DAW mode no longer removes Tap Tempo on User Buttons
- Issue with scribble strip screen and Asian characters now fixed (DAW mode crash, etc)
- FX Returns are now Post Fader to Auxes with Post Fader selected
- Phase setting now retains state on power cycle at 44.1kHz sample rate
- Studio One now at the top of the control list for DAW Mode when available
- Mixer's custom name now shows in preamp permissions for NSBs
- Hitting "Apply" for Preamp Permissions no longer resets AVB Sends
- Talkback Preamp gain now retained on power cycle at 44.1kHz sample rate
- DAW Mode now utilizes FlexMix Send view in Channel Overview screen properly
- Mixer no longer clears defaultProj/Scene for Default Admin profile when power-cycled
- FX Returns in Fixed Subgroups now work as expected after reboot at 44.1kHz sample rate
- RTA On SL64S Ch's 33-64 wot working properly with Network Input Source
- Solo Bus Pre Fader Listen now working as expected for channels 33-64 on SL64S
- HUI - Fat Channel Buttons for Automation now working properly
- RTA Pre/Post mode now working for outputs
- DAW Mode no longer breaks GEQ Assignment selection button UI

NSB 8/16

- Custom names now retained as expected after power cycle and firmware update
- Improved network / clock stability when units are powered for long periods of time

EarMix

- Custom names now retained as expected after power cycle and firmware update
- Panel and LED performance no longer gets sluggish over time.
- Improved network / clock stability when units are powered for long periods of time

Known Issues:

DAW Mode

- (Native Mode) When viewing a send or cue mix, send labels should be placed in the scribble strips
- (Native Mode) Incorrect preamp gain range on mixer display when using TRS inputs
- (Native Mode) Meters don't match between DAW mode and Mixer mode
- (Native Mode) Channel parameters may not populate in Fat Channel after opening song
- (Native Mode) Series III Automation Control: Bypass Button Not Present
- (Native Mode) Newly added Plugin not automatically selected and controls not on FatCh Encoder section if another Plugin wasn't already selected when adding the new Plugin
- (Native Mode) Talkback Button Does Not Light Up In UCS When Engaged From S1
- (Native Mode) Channel Input Does Not Have Selection For "None"
- (Native Mode) Unity Fader Value Is Not Accurate
- (Native Mode) There Is No Way To Remove A Channel Insert
- (Native Mode) Write Select Channel Should Turn Red Like FaderPort 8 & 16
- (Native Mode) Pressing Inputs layer button should open Inputs section in S1 Console
- (Native Mode) Adding Send while viewing Sends view doesn't update fader level
- (Native Mode) Select Buttons For Multi-Channel Instrument Outputs Do Not Light Up

Series III Mixers

- No FET Comp Input/Output Link Button
- Channels added to Series III Flex Mix Subgroups in UC while viewing the Subgroup on the Console do not update until selecting another Mix and returning to the Subgroup on the Console

If issues are experienced loading converted Scenes that were created on earlier firmware versions, it may be necessary to rebuild them.

Join our community of PreSonus users on the [PreSonus Answers](#) site for information and product support. While you're there, don't forget to vote for your favorite feature requests.

Alternatively, you can visit our [Knowledge Base](#) for more informative articles authored by the support staff. To log a support ticket or contact technical support, please visit [MyPreSonus](#).