

Universal Control 2.0.1 Milestone Release Notes

3/28/17

Version Information:

- Universal Control 2.0 (Mac/PC) - 2.0.1.42326
- UC Surface (iOS) - 2.0.1.42326
- QMix-UC (iOS/Android) - 2.0.1.42157
- Capture (Mac/PC) - 2.3.1.42326

UC 2.0 Supports the following Operating Systems:

- Windows 7 Service Pack 1 + Platform Update (32 bit & 64 bit)
- Windows 8.1 (32 bit & 64 bit)
- Windows 10 (32 bit & 64 bit)
- OS X 10.8.5 (Mountain Lion)
- OS X 10.9 (Mavericks)
- OS X 10.10 (Yosemite)
- OS X 10.11 (El Capitan)
- OS X 10.12 (Sierra)

Capture 2.3 is compatible with the following PreSonus Hardware and Software:

- StudioLive 16.4.2 classic
- StudioLive 24.4.2 classic
- StudioLive 16.0.2 classic
- StudioLive 16.4.2AI
- StudioLive 24.4.2AI
- StudioLive 32.4.2AI
- StudioLive RM32AI
- StudioLive RM16AI
- StudioLive RML32AI
- StudioLive RML16AI
- StudioLive AR8
- StudioLive AR12
- StudioLive AR16
- StudioLive 32 Series III
- StudioLive 16 Series III
- UC Surface 2.0.1

The Following iOS devices are Compatible with UC Surface (running iOS 9.3 or later):

- iPad (2nd generation)
- iPad (3rd generation)
- iPad (4th generation)
- iPad Mini
- iPad Mini 2
- iPad Mini 3
- iPad Mini 4
- iPad Air
- iPad Air 2
- iPad Pro

The Following iOS devices are Compatible with QMix-UC (running iOS 9.3 or later):

- iPhone 4S
- iPhone 5
- iPhone 5C
- iPhone 5S
- iPhone 6
- iPhone 6 Plus
- iPhone 6S
- iPhone 6S Plus
- iPhone SE
- iPhone 7
- iPhone 7 Plus
- iPod touch (5th Generation)
- iPod touch (6th Generation)

The Follow devices should be Compatible with Qmix-UC:

- Any device running Android 5.0 or later
- NOTE: Given the sheer number and variety of Android devices, there is no way to comprehensively qualify all devices that support Android 5.0 or later. Any device running Android 5.0 *should* work, but support and functionality may vary depending on the device.

UC 2.0 Does Not Support the Following Legacy Operating Systems:

- Versions of Windows 7 earlier than Service Pack 1 + Platform Update
- Windows 8 (users should update to Windows 8.1)

New In This Release:

- Universal Control / UC Surface support for StudioLive 16 Series III Mixers
- QMix-UC support for StudioLive 16 Series III Mixers
- UC Surface now defaults to FOH permissions when connected over Firewire or USB
- UC Surface Input Source selection improvements

Fixed In This Release:

UC Surface:

- Channel Type "Other" does not change Preset Category Filter
- Series III: Non-Standard EQ type should show mini-image of EQ model in ch. strip mini preview
- Series III: Fat Channel RTA Can Only Be Viewed If EQ Is On
- UC Surface shows FP8 firmware 1.02 as correct current version
- UC Surface + Notion no longer causes Studio 192 to Reset or Lock Up (Mac)
- Demo mode crashes when loading a scene
 - Disabled loading of scenes
- RM/AI Mixers: Fat Channel Copy/Paste always copies Ch.Name

Qmix-UC

- QMix-UC crash during connection condition now fixed for AI and RM mixers
- QMix-UC now grays out along with UC Surface for Studio 192 (Z-Mix in Studio One)

Capture

- Capture Main R record meter now present for Series III mixers

Known Issues:

UC Surface

- Control and metering for mixers connected over firewire exhibits lag
- Mute Group and Mix Scene custom names not persistent for AI family mixers
 - Not implemented in firmware yet
- Copy, Delete, & Rename Local Scenes for Cascaded mixers not functioning correctly
- Smart Wizard Go Remote Functionality missing
- RM/RML: Talkback source not retained after power cycle
- RM/RML: Fat Channel Reset Button Does Not Reset the HPF (or LPF)
- AI/RM Mixers: FX Bus Master is missing HPF control
- AI/RM Mixers: Restoring a Mixer Backup over Firewire is not possible. Must be done over Network connection
- AI/RM Mixers: Auxiliary Firewire Input 52 driver label is incorrect
- AI Consoles: No Gain Reduction meter in the Ch. Strip next to the Input meter
- AI Consoles: Solo level missing from UC Surface
- AI Consoles: Can not edit Mute Group and Mix Scene names
 - Not implemented in firmware yet
- AI Consoles: Channel Type and Channel Color not persistent or shared across clients
 - Not implemented in firmware yet

Qmix-UC

- QMix-UC has no permissions capability for Studio 192

Capture

- Playback routing incorrect with cascaded classic StudioLive 16.4.2 consoles

Join our community of PreSonus users on the [PreSonus Forum](#) for information, user-based support, tips and tricks, and more.

Alternatively, you can visit our [Knowledge Base](#) for more informative articles authored by the support staff. To log a support ticket or contact technical support, please visit [MyPreSonus](#).