Version Information:

- Universal Control 2.0 (Mac/PC) 2.1.43180
- UC Surface (iOS) 2.1.43180
- QMix-UC (iOS/Android) 2.0.1.42157
- Capture (Mac/PC) 2.3.2.43180

UC 2.0 Supports the following Operating Systems:

- Windows 7 Service Pack 1 + Platform Update (32 bit & 64 bit)
- Windows 8.1 (32 bit & 64 bit)
- Windows 10 (32 bit & 64 bit)
- OS X 10.8.5 (Mountain Lion)
- OS X 10.9 (Mavericks)
- OS X 10.10 (Yosemite)
- OS X 10.11 (El Capitan)
- OS X 10.12 (Sierra)

Capture 2.3 is compatible with the following PreSonus Hardware and Software:

- StudioLive 16.4.2 classic
- StudioLive 24.4.2 classic
- StudioLive 16.0.2 classic
- StudioLive 16.4.2AI
- StudioLive 24.4.2Al
- StudioLive 32.4.2Al
- StudioLive RM32AI
- StudioLive RM16AI
- StudioLive RML32AI
- StudioLive RML16AI
- StudioLive AR8
- StudioLive AR12
- StudioLive AR16
- StudioLive 32 Series III
- StudioLive 24 Series III.
- StudioLive 16 Series III
- UC Surface 2.1

The Following iOS devices are Compatible with UC Surface (running iOS 9.3 or later):

- iPad (2nd generation)
- iPad (3rd generation)
- iPad (4th generation)
- iPad Mini
- iPad Mini 2
- iPad Mini 3
- iPad Mini 4
- iPad Air
- iPad Air 2
- iPad Pro

The Following iOS devices are Compatible with QMix-UC (running iOS 9.3 or later):

- iPhone 4S
- iPhone 5
- iPhone 5C
- iPhone 5S
- iPhone 6
- iPhone 6 Plus
- iPhone 6S
- iPhone 6S Plus
- iPhone SE
- iPhone 7
- iPhone 7 Plus
- iPod touch (5th Generation)
- iPod touch (6th Generation)

The Follow devices should be Compatible with Qmix-UC:

• Any device running Android 5.0 or later

NOTE: Given the sheer number and variety of Android devices, there is no way to comprehensively qualify all devices that support Android 5.0 or later. Any device running Android 5.0 should work, but support and functionality may vary depending on the device.

UC 2.0 Does Not Support the Following Legacy Operating Systems:

- Versions of Windows 7 earlier than Service Pack 1 + Platform Update
- Windows 8 (users should update to Windows 8.1)

New In This Release:

- Universal Control support for Quantum interface
- Contrast control for FaderPort 8 scribble strips now available with included firmware update

Fixed In This Release:

UC Surface:

- Capture Remote no longer disconnects when iPad switches apps/screen sleeps
- iOS: Text Entry no longer shows "Copy To Clipboard" popup

FaderPort 8:

Section enables FF and RW control from Session Nav and can now be turned off in Sonar

Known Issues:

UC Surface

- Series III: SL16 and SL24 PC driver labels not shown correctly in Windows Sound Properties
- Control and metering on UC Surface instance connected via Firewire may exhibit lag on some systems
- Copy, Delete, & Rename Local Scenes for Cascaded mixers not functioning as expected
- RM/RML: Fat Channel Reset Button Does Not Reset the HPF (or LPF)
- Al/RM Mixers: FX Bus Master is missing HPF control
- Al/RM Mixers: Restoring a Mixer Backup over Firewire is not possible.
 - o Must be done over Network connection
- Al/RM Mixers: Auxiliary Firewire Input 52 driver label is incorrect
- Al Consoles: Solo level missing from Settings page
- Al Consoles: Channel Type and Channel Color not persistent or shared across clients
 - Not implemented in firmware yet

Capture

Playback routing incorrect with cascaded classic StudioLive 16.4.2 consoles

Join our community of PreSonus users on the <u>PreSonus Answers</u> site for information and product support. While you're there, don't forget to vote for your favorite feature requests.

Alternatively, you can visit our <u>Knowledge Base</u> for more informative articles authored by the support staff. To log a support ticket or contact technical support, please visit <u>MyPreSonus</u>.