

## Universal Control 2.0 Release Notes

### **Version Information:**

- Universal Control 2.0 (Mac/PC) - 2.0.0.41902
- UC Surface (iOS) - 2.0.0.41902
- QMix-UC (iOS/Android) - 2.0.0.41911
- Capture (Mac/PC) - 2.3.0.41943

### **New In This Release:**

- UC 2.0 updates and replaces UC 1.8.3 (same mixers/interfaces supported)
  - New look and layout
  - New View Modes: Fat Channel, Sends, and Meters view
  - New Setup Options and improvements: Dark/Light color scheme adjustment, Custom Channel Colors, Colorize Channel Strips, Channel ID options, fast channel naming using Tab to next channel, Show Edit Popup
  - Channel Select Sync follow mode
  - New Flex Fader functionality for Main bus
  - Improved Scene and Preset management
  - HPF now drawn as part of Fat Channel EQ curve
  - Improvements to Parameter Edit Popups
  - Parameter Edit via Text Entry
  - Ctrl/Cmd+click to Reset Parameters
  - Resizeable and Maximizable Application Window
  - AI Consoles: Dedicated Subgroup Assign buttons in Fat Channel
  - Remote device connection maintenance improvements
- QMix-UC updates and replaces QMix-AI (same mixers/interfaces supported)
  - New look and layout
  - New Features: Channel Groups with Grouped control in landscape mixer view and Group Master Fader control in portrait view, UC Surface style Pan controls in Stereo Mixes
  - Now shows and controls cascaded RM/RML mixers as a single 64 channel mixer
  - Support for Android devices
  - Studio 192 / Studio 192 Mobile support added **\*BETA**
  - Remote device connection maintenance improvements

### **UC 2.0 Supports the following Operating Systems:**

- Windows 7 Service Pack 1 + Platform Update (32 bit & 64 bit)
- Windows 8.1 (32 bit & 64 bit)
- Windows 10 (32 bit & 64 bit)
- OS X 10.8.5 (Mountain Lion)
- OS X 10.9 (Mavericks)
- OS X 10.10 (Yosemite)
- OS X 10.11 (El Capitan)
- OS X 10.12 (Sierra)

**Capture 2.3 Supports the following PreSonus Hardware and Software:**

- StudioLive 16.4.2
- StudioLive 24.4.2
- StudioLive 16.0.2
- StudioLive 16.4.2AI
- StudioLive 24.4.2AI
- StudioLive 32.4.2AI
- StudioLive RM32AI
- StudioLive RM16AI
- StudioLive RML32AI
- StudioLive RML16AI
- StudioLive AR8
- StudioLive AR12
- StudioLive AR16
- StudioLive 32 Series III
- UC Surface 2.0
- FaderPort 8

**The Following iOS devices are Compatible with UC Surface (running iOS 9 or later):**

- iPad (2nd generation)
- iPad (3rd generation)
- iPad (4th generation)
- iPad Mini
- iPad Mini 2
- iPad Mini 3
- iPad Mini 4
- iPad Air
- iPad Air 2
- iPad Pro

**The Following iOS devices are Compatible with QMix-UC (running iOS 9 or later):**

- iPhone 4S
- iPhone 5
- iPhone 5C
- iPhone 5S
- iPhone 6
- iPhone 6 Plus
- iPhone 6S
- iPhone 6S Plus
- iPhone SE
- iPhone 7
- iPhone 7 Plus
- iPod touch (5th Generation)
- iPod touch (6th Generation)

### **The Follow devices should be Compatible with Qmix-UC:**

- Any device running Android 5.0 or later
- NOTE: Given the sheer number and variety of Android devices, there is no way to comprehensively qualify all devices that support Android 5.0 or later. Any device running Android 5.0 *should* work, but support and functionality may vary depending on the device.

### **UC 2.0 Does Not Support the Following Legacy Operating Systems:**

- Versions of Windows 7 earlier than Service Pack 1 + Platform Update
- Windows 8 (users should update to Windows 8.1)

### **Known Issues:**

#### **UC Surface**

- Series III: WDM channels should be routed to Mixer Sends>Returns 37 & 38, not 1 & 2
- Control and metering for mixers connected over firewire is too slow
- Mute Group and Mix Scene custom names not persistent for AI family mixers
- UC Surface + Notion Causes Studio 192 to Reset or Lock Up (Mac)
- Copy, Delete, & Rename local Scenes for Cascaded mixers not functioning correctly
- Should default to Edit mode when Selecting an empty Subgroup
- Smart Wizard Go Remote Functionality missing
- RM/RML Talkback source not retained after power cycle
- RM Mixers Fat Channel Reset Button Does Not Reset the HPF (or LPF)
- AI/RM Mixers: Restoring a Mixer Backup over Firewire is not possible. Must be done over Network connection
- AI/RM Mixers: Auxiliary Firewire Input 52 driver label is incorrect
- AI Consoles: No Gain Reduction meter in the Ch. Strip next to the Input meter
- AI Consoles: Solo level missing from UC Surface
- AI Consoles: Can not edit Mute Group and Mix Scene names

#### **Qmix-UC**

- QMix-UC has no permissions capability for Studio 192

#### **Capture**

- Main R meter for Series III mixers not shown (Main L meter is present)
- Playback routing incorrect with cascaded classic StudioLive 16.4.2 consoles

Join our community of PreSonus users on the [PreSonus Forum](#) for information, user-based support, tips and tricks, and more.

Alternatively, you can visit our [Knowledge Base](#) for more informative articles authored by the support staff. To log a support ticket or contact technical support, please visit [MyPreSonus](#).