

Worx Control 1.5.58513 Release Notes

Date: 6-23-2020

OS Support:

- Windows 7 SP1 + Platform Update, Windows 8.1, and Windows 10 x64 v1903, 1909, and 2004 (no 32 bit support)
- macOS 10.11 - 10.15

Firmware released with this version: v1.5.17012 (PDA 1K & 2K models)

Fixed or added in this release:

- Fixed an issue with PDA2000 Amps in Linked Mode, where this control link would be broken when the Master Amp is moved into a Group.
- Fixed issue with PDA (1k and 2k) amps with older firmware having incorrect amp settings after updating to version from a version older than 1.3 release.

Note: *PDA Amplifier firmware must be updated to the latest version to be fully compatible with Worx Control 1.5. It is suggested to update Worx Control before applying firmware.*