

AudioBox 1.2.2 (build 5461)

This build fixes issues of random pops and clicks on Mac systems during normal recording and playback

Compatible Interfaces:

- AudioBox USB
- AudioBox 22 VSL
- AudioBox 44 VSL
- AudioBox 1818 VSL

Supported Operating Systems

- Mac OS X 10.6.8 (Snow Leopard)
- Mac OS X 10.7.5 (Lion)
- Mac OS X 10.8 (Mountain Lion)

Supported iOS App(s)

- AB1818VSL Remote

Known Issues

- Occasional pops/click when clocking via ADAT with AudioBox 1818 VSL