

July 21, 2014

AudioBox 1.3 Family Driver Release Notes

Supported Products:

- AudioBox USB
- AudioBox 22VSL
- AudioBox 44VSL
- AudioBox 1818VSL

Products Added:

- AudioBox iOne
- AudioBox iTwo

Improvements:

- Distortion issues found with USB 3.0 chipsets and Intel I-Series processors
 - Customers with USB 3.0 capable systems who are running Mavericks 10.9 must be on 10.9.4 minimum for their AudioBox series device to work correctly.
 - Apple updated their USB 3.0 driver with Mac OS X 10.9.4.

Other Changes:

- Added support for Windows 8.1
- Installer will warn if system is below recommended requirements
 - Removed support for Windows XP, Vista
 - Removed installation support for 10.7 and older Mac OS X systems
- Improvements made for working with Windows System Audio
- MIDI OUT pipe throughput increased
 - MIDI OUT pipe sends 2 and 3 byte events now as defined by the MIDI spec.
 - Single Byte event (0xF) is not used anymore.

Driver Version: 2.21.0 (Build 5636)

AudioBox 1.3 is supported with the following Operating Systems:

- Windows 8 and Windows 8.1 (32 bit & 64 bit)
- Windows 7 Service Pack 1 (32 bit & 64 bit)
- Mac OS X 10.8.x and 10.9.4

Note: Driver Version Naming

- AudioBox 1.3 is a cosmetic name that encompasses all of the software packages and devices together as a series. The individual driver, firmware and application versions will vary based on device and install.
- For a complete breakdown of firmware, driver and application version see list below.

**Audiobox Family Series 1.3
Driver and Firmware Version Numbers By Product**

Audiobox USB

PC: Driver Version - 2.21.0.5653
MAC: No Driver - Class Compliant

Audiobox 22VSL

PC: Driver Version - 2.21.0.5653
Firmware Version - 1.06

MAC: Driver Version - 1.50.0.5653
Firmware Version - 1.06

Audiobox 44VSL

PC: Driver Version - 2.21.0.5653
Firmware Version - 1.05

MAC: Driver Version - 1.50.0.5653
Firmware Version - 1.05

Audiobox 1818VSL

PC: Driver Version - 2.21.0.5653
Firmware Version 1.18

MAC: Driver Version 1.50.0.5653
Firmware Version 1.18

Audiobox iOne

PC: Driver Version - 2.21.0.5653
Application Version - 1.3.5653
Firmware Version - 1.25

MAC: Driver Version -
Mac OS X 10.9 Mavericks: 1.80.0.5653
Mac OS X 10.8 Mountain Lion: 1.81.0.5653
Application Version - 1.3.5653
Firmware Version - 1.25

Audiobox iTwo

PC: Driver Version - 2.21.0.5653
Application Version - 1.3.5653
Firmware Version - 1.25

MAC: Driver Version -
Mac OS X 10.9 Mavericks: 1.80.0.5653
Mac OS X 10.8 Mountain Lion: 1.81.0.5653
Application Version - 1.3.5653
Firmware Version - 1.25

Join our community of PreSonus users at <http://forums.preonus.com> for information, user-based support, tips and tricks, and more. Alternatively you can visit our [Knowledge Base](#) for more informative articles authored by the support staff. To log a support ticket or contact technical support, please visit <http://my.preonus.com>.