

This update to Universal Control for PreSonus FireStudio Interfaces and Gen 1 StudioLive Mixers is to support the updated 64-bit versions of SL Remote and QMix Apps so they may continue to be supported on iOS 11. This update requires that SL Remote, QMix, and UC are all on the latest version in order to work properly. Not updating any of these Apps or the UC software can result in App connection & control issues for the selected mixer related to device permissions errors.

NOTE: Simultaneous operation of or daisy-chaining of StudioLive AI mixers with FireStudio interfaces or 1st generation StudioLive mixers is not supported. This driver and control panel will not control the new StudioLive AI series mixers.

Universal Control 1.7.4.5 includes drivers and control panels for the following products:

- FireStudio Mobile™ (Launch Window, Device Mixer, Driver)
- FireStudio Project™ (Launch Window, Device Mixer, Driver)
- FireStudio Tube™ (Launch Window, Device Mixer, Driver)
- FireStudio Lightpipe™ (Launch Window, Device Mixer, Driver)
- StudioLive™ 16.0.2 (Launch Window, Virtual StudioLive, Driver)
- StudioLive 16.4.2 (Launch Window, Virtual StudioLive, Driver)
- StudioLive 24.4.2 (Launch Window, Virtual StudioLive, Driver)

StudioLive firmware and build information:

- 16.0.2: Firmware Version 0.98f, build 219
- 16.4.2: Firmware Version 1.50a, build 190
- 24.4.2: Firmware Version 1.0, build 195

Driver Version: 4.2.1.46437

Universal Control Build:

- Mac - 1.7.4.5848

Universal Control 1.7.4.5 Officially Supports the following Operating Systems:

- OS X 10.9.5 (Mavericks)
- OS X 10.10 (Yosemite)
- OS X 10.11 (El Capitan)
- OS X 10.12 (Sierra)

Current App versions compatible with this Universal Control release:

- SL Remote 1.6.5 for iPad®
- QMix 1.4.5 for iPhone® and iPod Touch®

The Following iOS Devices are Compatible with SL Remote (running iOS 8 or later):

- iPad 2nd generation
- iPad 3rd generation
- iPad 4rd generation
- iPad Mini
- iPad Mini 2
- iPad Mini 3
- iPad Mini 4
- iPad Air
- iPad Air 2
- iPad Pro

The Following iOS Devices are Compatible with QMix (running iOS 8 or later):

- iPhone 4
- iPhone 4S
- iPhone 5
- iPhone 5C
- iPhone 5S
- iPhone 6
- iPhone 6 Plus
- iPhone 6S
- iPhone 6S Plus
- iPhone SE
- iPod touch (5th Generation)
- iPod touch (6th Generation)

Universal Control Version 1.7.4.5 Does Not Support the Following Products or Operating Systems:

- FireStudio (26x26)
- OS X 10.8.5 (Mountain Lion) or earlier

Known Issues

- When the StudioLive 24.4.2 Subgroup Delay time is between 1050 ms, the last digit is partially cut off
- Non-Western Characters in the name of iOS device will show up in the VSL Remote Devices Section as ??????
- When UC is Quit on Mac, a message is displayed after the App closes, which says that the App crashed. This does not affect functionality of UC.

Universal Control Update Instructions:

1. Quit out of Universal Control and disconnect your device from the computer.
2. Run the installer and follow the onscreen instructions. The installer requires that your computer be rebooted upon successful completion.
3. Once your computer has restarted, connect your FireStudio or StudioLive series device and open Universal Control.

Join our community of PreSonus users on the [PreSonus Forum](#) for information, user-based support, tips and tricks, and more.

Alternatively, you can visit our [Knowledge Base](#) for more informative articles authored by the support staff. To log a support ticket or contact technical support, please visit [MyPreSonus](#).