


Dec 21, 2018


PreSonus CDL Firmware Update Instructions.

These instructions work for both Mac and Windows computer systems.


- 1: Install Worx Control 1.2.49773 and run the application.
- 2: Close Worx Control.
- 3: Open your Documents folder
- 4: Open folder named "PreSonus"
- 5: Open folder named "Worx Control"
- 6: Open folder named "DFU"
- 7: Copy and Paste the folder named "PDA1000_Firmware_Update_v15198" into the DFU folder.
- 8: Run Worx Control
- 9: Create a new Venue or open an existing one.
- 10: Select your CDL Speaker Setup icon (Cog Wheel)



11. On the right side of the screen of the Speaker Edit window click the Hamburger Icon to open the Firmware Update Screen.



12. Select the Firmware in Update browser Window and click “Update Firmware”



Firmware Update will run and when done, the Speaker will reboot on it's own. It will disappear from Worx Control and reappear when it has come back online.

To confirm firmware version, look at the bottom of the edit screen to see Firmware Version loaded on that speaker. It should say: SL 1.2.15198

